

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AB154
WSW
1/4-1/2
0.278 mi.
1470 ft.

AT EXCAVATION SITE
NEPTUNE AVE AND WEST 16TH ST
BROOKLYN, NY

NY Spills **S113493910**
N/A

Site 2 of 5 in cluster AB

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: AT EXCAVATION SITE
Address: NEPTUNE AVE AND WEST 16TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1301403 / 2016-03-30
Facility ID: 1301403
Facility Type: ER
DER Facility ID: 437035
Site ID: 481782

DEC Region: 2
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Spill Date: 2013-05-10
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2013-05-10
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-05-10
Spill Record Last Update: 2016-03-30
Spiller Name: Not reported
Spiller Company: UNKNOWN - ?NATIONAL GRID
Spiller Address: Not reported
Spiller Company: 999
Contact Name: DEANNA BROWN
DEC Memo: "Sangesland left voicemail message with Deanna at DEP looking for more information. case closed due to insufficient information."

Remarks: "cleanup pending investigation"

All Materials:

Site ID: 481782
Operable Unit ID: 1231547
Operable Unit: 01
Material ID: 2230309
Material Code: 0064A
Material Name: unknown material
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported